



Since 1938

2017 CLASS II, III & IV TRAILER HITCH APPLICATIONS

Always check your owners manual for the maximum towing and load capacities for your vehicle.

Questions? Call 800-821-7576 or 816-921-0444 Monday through Friday, 8:00-4:30 CST.

Part numbers printed in red indicate no drilling required.

SEE
COUNTER
PERSON FOR
SPECIAL
ORDERS

| ACME APPLICATIONS BY VEHICLE | | Class II Receiver | | Class III Receiver | | Class IV Receiver | | |
|---|-----------|--|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|
| VEHICLE MAKE & MODEL | YEAR | Universal to 3500 lbs 1 1/4" Receiver | One Piece to 3500 lbs 2" Receiver | Universal to 5000 lbs 2" Receiver | One Piece to 5000 lbs 2" Receiver | Universal to 7500 lbs 2" Receiver | One Piece to 7500 lbs 2" Receiver | One Piece to 10,000 lbs 2" Receiver |
| | | BUICK | | | | | | |
| Enclave | 2007-2017 | | | | 91538 (0) | | | |
| Terraza | 2005-2007 | | 91456 (0) | | | | | |
| CHEVROLET TRUCKS & VANS | | | | | | | | |
| Astrovan Standard | 1985-94 | 88202 (0) | 91446 (4) | | | | | |
| Astrovan Extended | 1985-2005 | 88202 (0) | 91446 (0) | | | | | |
| Avalanche | 2002-2006 | | | | | | 91472 (0) | |
| Blazer, Full Size | 1978-87 | 88202 (4) | | | | | | |
| Blazer, Full Size | 1992-94 | | | | | | 91430 (0) | |
| Tahoe, Classic | 1995-2000 | | | | | | 91430 (0) | |
| Tahoe, New Style | 2000-2006 | | | | | | 91472 (0) | |
| Blazer, S-10 | 1983-94 | 88202 (2) | | | 91438 (0) | | | |
| Blazer, Downsized | 1995-2005 | | | | 91434 (4) | | | |
| Colorado | 2004-2012 | | | | 91495 (0) | | | |
| Colorado | 2015-2017 | | | | | | 91540 (0) M | |
| Equinox | 2005-2017 | | 91512 (0) | | | | | |
| Luv | 1981-82 | 88202 (4) | | | | | | |
| Pickup, Full Size | 1968-87 | | | 88302 (4) I | | | 91403 (6) | |
| Pickup, Full Size With 10" Drop Bumper | 1988-98 | | | 88302 (2) I | | 91409 (0) | 91404 (2) I | 91406 (0) |
| Pickup, Full Size With 12" Drop Bumper | | | | | | | | 91460 (0) |
| Pickup, Classic C/K Series 3/4 & 1-Ton | 1999-2000 | | | | | 91409 (0) | | 91458 (0) |
| Pickup, Classic C/K Series With 10" Drop Bumper | | | | | | | | 91406 (0) |
| Pickup, Classic C/K Series With 12" Drop Bumper | | | | | | | | 91460 (0) |
| Pickup, Silverado, 1500 LD, 1500 HD & 2500 LD | 1999-2006 | | | | | 91409 (2) | | 91454 (0) |
| Pickup, Classic Silverado, 1500 LD & 1500 HD | 2007 | | | | | 91409 (2) | | 91454 (0) |
| Pickup, Silverado, 1500 (New Body Style) | 2007-2017 | | | | | | | 91510 (0) |
| Pickup, Silverado, 2500 HD & 3500 Shortbed Only | 2001-2006 | | | | | | | 91477 (0) |
| Pickup, Silverado, 2500 HD & 3500 Shortbed Only (Classic & New Body Style) | 2007-2010 | | | | | | | 91478 (0) |
| Pickup, Silverado, 2500 HD & 3500 Longbed Only | 2001-2006 | | | | | | | 91478 (0) |
| Pickup, Silverado, 2500 HD & 3500 Longbed Only (Classic & New Body Style) | 2007-2010 | | | | | | | 91478 (0) |
| Pickup, Silverado, 2500 HD & 3500 Longbed Only w/ 10" Drop Bumper | 2001-2010 | | | | | | | 91515 (0) |
| Pickup, Silverado, 2500 HD & 3500 Longbed Only w/ 10" Drop Bumper | 2011-2017 | | | | | | | 91527 (0) |
| Pickup, Silverado, 2500 HD & 3500 Longbed Only | 2011-2017 | | | | | | | 91525 (0) |
| Pickup, Silverado, 2500 HD & 3500 Shortbed Only | 2011-2017 | | | | | | | 91529 (0) |
| Pickup, 3500 Cab & Chassis | 1999-2013 | | | | | | | 91602 (10) L 91603 (10) L |
| Pickup, S-10 | 1982-93 | 88202 (4) A | | | 91435 (4) | | | |
| Pickup, S-10 Longbed Only | 1982-93 | 88202 (4) | | 88302 (6) ** A | 91435 (4) | | | |
| Pickup, S-10 Sportside | 1994-2004 | | | | 91485 (0) | | | |
| Pickup, S-10 (Except Sportside) | 1994-2004 | 88202 (4) A | | | 91436 (0) | | | |
| Suburban | 1973-91 | | | | | | 91480 (4) | |
| Suburban, Classic | 1992-99 | | | | | | 91430 (0) | |
| Suburban, New Style | 2000-2006 | | | | | | 91472 (0) | |
| Geo Tracker | 1989-98 | 88202 (0) | | | | | | |
| Tracker | 1999-2004 | 88202 (0) | 91468 (0) | | | | | |
| Traverse | 2009-2017 | | | | 91538 (0) | | | |
| Uplander | 2005-2009 | | 91456 (0) | | | | | |
| Van, Full Size | 1978-95 | | | | | | 91447 (0) | |
| Van, Full Size, Express | 1996-2017 | | | | | | 91431 (0) | |
| Venture Minivan | 1997-2005 | | 91456 (0) | | | | | |
| CHRYSLER VANS | | | | | | | | |
| Aspen | 2007-2008 | | | | | | 91497 (0) | |
| Town & Country Minivan | 1991-95 | 88203 (0) | | | | | | |
| Town & Country Minivan (Except Stow N Go Seats) | 1996-2006 | 88203 (2) G | 91470 (0) | | | | | |
| Town & Country Minivan With Stow N Go Seats | 2005-2007 | | 91507 (0) | | | | | |
| Town & Country Minivan | 2008-2016 | | 91514 (0) | | | | | |

(A) May require some exhaust pipe modification, or relocation of tailpipe holder.

(B) Spare tire holder must be moved.

(C) Do not mount frame arm against brake line.

(D) Gas tank must be dropped to install bolts through frame.

(E) Maximum rating on Windstar is 2000 lbs. GTW.

(F) Make sure gas tank filter hose does not rub on hitch.

(G) Full size spare must be moved.

(H) Must relocate spare if equipped with 17" wheels

(I) 1/2 ton only.

(J) 1 1/4" Receiver.

(L) Combination pintle mount (16,000 lbs.) and receiver hitch (10,000 lbs.)

(M) Max. Gross Trailer Weight - 6,000 lbs.

** 4 Wheel Drive Only

(#) = Number of holes to be drilled in frame. Example - Ford Ranger Pickup 1983-2011 Hitch 91440 (0) = 0 holes to be drilled.



Since 1938

2017 CLASS II, III & IV TRAILER HITCH APPLICATIONS

Always check your owners manual for the maximum towing and load capacities for your vehicle.

Questions? Call 800-821-7576 or 816-921-0444 Monday through Friday, 8:00-4:30 CST.

Part numbers printed in red indicate no drilling required.

SEE
COUNTER
PERSON FOR
SPECIAL
ORDERS

| ACME APPLICATIONS BY VEHICLE | | Class II Receiver | | Class III Receiver | | Class IV Receiver | | |
|--|-----------|--|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|
| | | Universal to 3500 lbs 1 1/4" Receiver | One Piece to 3500 lbs 2" Receiver | Universal to 5000 lbs 2" Receiver | One Piece to 5000 lbs 2" Receiver | Universal to 7500 lbs 2" Receiver | One Piece to 7500 lbs 2" Receiver | One Piece to 10,000 lbs 2" Receiver |
| VEHICLE MAKE & MODEL | YEAR | | | | | | | |
| DODGE TRUCKS & VANS | | | | | | | | |
| Caravan & Grand Caravan | 1984-90 | 88202 (2) C | | | | | | |
| Caravan & Grand Caravan | 1991-95 | 88203 (0) | | | | | | |
| Caravan & Grand Caravan (Except Stow N Go Seats) | 1996-2006 | 88203 (2) G | 91470 (0) | | | | | |
| Grand Caravan With Stow N Go Seats | 2005-2007 | | 91507 (0) | | | | | |
| Grand Caravan | 2008-2017 | | 91514 (0) | | | | | |
| Dakota, All | 1987-96 | | | 88302 (2) | | | | |
| Dakota, All | 1997-2004 | | | 88302 (4) | | 91409 (2) A | 91450 (2) | |
| Dakota, All | 2005-2011 | | | | | | 91508 (0) | |
| Durango | 1998-2003 | | | | 91461 (2) | | | |
| Durango | 2004-2010 | | | | | | 91497 (0) | |
| Durango | 2011-2017 | | | | 91531 (0) | | | |
| Pickup, Full Size, All | 1974-93 | | | 88302 (2) | | | 91405 (2) | |
| Pickup, Full Size, Shortbed, All | 1994-98 | | | 88302 (4) | | 91409 (2) | 91405 (2) | 91407 (0) |
| Pickup, Full Size, Longbed, All | 1994-98 | | | 88302 (4) | | 91409 (0) | 91405 (2) | 91407 (0) |
| Pickup, Full Size, All | 1994-98 | | | | | | | 91490 (0) |
| With 10" Drop Bumper | | | | | | | | 91491 (0) |
| With 12" Drop Bumper | | | | | | | | 91465 (2) |
| Pickup, Full Size, Shortbed, All | 1999-2001 | | | | | 91409 (2) | | 91465 (2) |
| Pickup, Full Size, Longbed, All | 1999-2001 | | | | | 91409 (0) | | 91465 (0) |
| Pickup, Full Size, Quad Cab | 2001 | | | | | 91409 (2) | | 91465 (2) |
| Pickup, Full Size 2500 & 3500 | 2002 | | | | | 91409 (2) | | 91465 (2) |
| Pickup, Full Size, 1500 | 2002 | | | | 91489 (0) | | | 91488 (6) |
| Pickup, Full Size, All (Built after 11/2002) | 2003-2008 | | | | | | 91522 (0) M | 91488 (6) |
| Pickup, Full Size, 2500 & 3500 | 2009-2010 | | | | | | 91522 (0) M | 91488 (6) |
| Pickup, Full Size, 1500 | 2009-2010 | | | | | | 91522 (0) M | |
| RAM 1500 | 2011-2017 | | | | | | 91522 (0) M | |
| RAM 2500 & 3500 | 2011-2017 | | | | | | 91522 (0) M | 91488 (6) |
| RAM C/V Minivan | 2012-2015 | | 91514 (0) | | | | | |
| Ramcharger | 1974-77 | | | 88302 (6) | | | | |
| Ramcharger | 1978-93 | 88202 (2) | | 88302 (4) | | | | |
| Van, Full Size | 1978-80 | 88202 (4) | | | | | | |
| Van, Full Size | 1978-97 | | | | 91437 (0) F | | | |
| Van, Full Size | 1998-2004 | | | 88302 (4) | 91462 (0) | | | |
| FORD TRUCKS & VANS | | | | | | | | |
| Bronco, Full Size | 1978-96 | | | 88302 (6) D | | | | |
| Bronco, Full Size | 1988-96 | | | | | 91409 (4) D | 91404 (6) D | 91406 (6) D |
| Bronco II | 1984-90 | 88202 (4) B | | | | | | |
| Escape | 2001-2004 | | 91482 (4) | | | | | |
| Escape (except Hybrid) | 2005-2012 | | 91499 (1) | | | | | |
| Explorer | 1991-94 | 88202 (4) | | | 91464 (2) | | | |
| Explorer | 1995-2001 | 88202 (4) | | | 91464 (0) | | | |
| Explorer Sport | 2002-2003 | | | | 91464 (0) | | | |
| Explorer Sport Trac | 2001-2005 | | | | 91474 (0) | | | |
| Expedition | 1997-2002 | | | | | | 91449 (2) | |
| Pickup, Full Size, All | 1973-96 | | | 88302 (6) | | 91409 (4) | 91405 (6) | 91407 (6) |
| | | | | | | | | 91465 (6) |
| Pickup, Full Size, With 10" Drop Bumper | 1973-96 | | | | | | | 91490 (6) |
| With 12" Drop Bumper | | | | | | | | 91491 (6) |
| Pickup, Full Size, HD F250 & F350 | 1997 | | | 88302 (6) | | 91409 (4) | 91405 (6) | 91407 (6) |
| | | | | | | | | 91465 (6) |
| Pickup, HD F250 & F350 | 1997 | | | | | | | 91490 (6) |
| With 10" Drop Bumper | | | | | | | | 91491 (6) |
| With 12" Drop Bumper | | | | | | | | 91448 (0) |
| Pickup, Full Size, F150 & F250 LD | 1997-2003 | | | 88302 (4) H | | 91409 (2) H | | 91448 (0) |
| Pickup, F150, Super Crew | 2001-2003 | | | | | 91409 (2) | | 91448 (0) |
| Pickup, Full Size, F150 Heritage | 2004 | | | 88302 (4) H | | 91409 (2) H | | 91448 (0) |
| Pickup, Full Size, F150 & Super Crew | 2004-2005 | | | | | | | 91494 (6) |
| Pickup, Full Size, F150 | 2006-2008 | | | | | | | 91506 (0) |
| Pickup, Full Size, F150 | 2009-2014 | | | | | | 91518 (0) M | |
| Pickup, Full Size, F150 | 2015-2017 | | | | | | 91539 (0) M | |
| Pickup, Full Size, SD F250 & F350 | 1999-2016 | | | | | 91409 (0) | | 91459 (0) |
| Pickup, Full Size, SD F250 & F350 | 1999-2016 | | | | | | | 91519 (0) |
| with 10" Drop Bumper | | | | | | | | 91542 (0) |
| Pickup, Full Size, SD F250 & 350 | 2017 | | | | | | | 91471 (2) L |
| Pickup, F350-F550, Cab & Chassis | 1999-2017 | | | | | | | 91481 (2) |
| | | | | | | | | 91601 (2) L |
| Ranger | 1983-2011 | 88202 (0) | 91475 (0) J | | 91440 (0) | | | |
| Transit, 150-350 | 2015-2017 | | | | | | 91536 (0) M | |
| Van, Aerostar | 1986-97 | 88202 (4) B | | | | | | |
| Van, Aerostar Extended | 1986-97 | 88202 (4) | 91443 (4) | 88302 (6) | | | | |
| Van, Freestar | 2004-2007 | | 91505 (0) | | | | | |

(A) May require some exhaust pipe modification, or relocation of tailpipe holder.
 (B) Spare tire holder must be moved.
 (C) Do not mount frame arm against brake line.
 (D) Gas tank must be dropped to install bolts through frame.

(E) Maximum rating on Windstar is 2000 lbs. GTW.
 (F) Make sure gas tank filter hose does not rub on hitch.
 (G) Full size spare must be moved.
 (H) Must relocate spare if equipped with 17" wheels
 (I) 1/2 ton only.

(J) 1 1/4" Receiver.
 (L) Combination pintle mount (16,000 lbs.) and receiver hitch (10,000 lbs.)
 (M) Max. Gross Trailer Weight - 6,000 lbs.
 ** 4 Wheel Drive Only

(#) = Number of holes to be drilled in frame. Example - Ford Ranger Pickup 1983-2011 Hitch 91440 (0) = 0 holes to be drilled.



2017 CLASS II, III & IV TRAILER HITCH APPLICATIONS

Always check your owners manual for the maximum towing and load capacities for your vehicle.

Questions? Call 800-821-7576 or 816-921-0444 Monday through Friday, 8:00-4:30 CST.

SEE
COUNTER
PERSON FOR
SPECIAL
ORDERS

Since 1938

Part numbers printed in red indicate no drilling required.

| ACME APPLICATIONS BY VEHICLE | | Class II Receiver | | Class III Receiver | | Class IV Receiver | | |
|--|-----------|--|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|
| | | Universal to 3500 lbs 1 1/4" Receiver | One Piece to 3500 lbs 2" Receiver | Universal to 5000 lbs 2" Receiver | One Piece to 5000 lbs 2" Receiver | Universal to 7500 lbs 2" Receiver | One Piece to 7500 lbs 2" Receiver | One Piece to 10,000 lbs 2" Receiver |
| VEHICLE MAKE & MODEL | YEAR | | | | | | | |
| FORD TRUCKS & VANS - CONTINUED | | | | | | | | |
| Van, Full Size | 1980-91 | | | | | | | 91432 (2) |
| Van, Full Size | 1992-2014 | 88202 (2) | | | | | | 91432 (2) |
| Van, Windstar | 1995-2004 | 88203 (2) E | 91473 (2) E | | | | | |
| GMC TRUCKS & VANS | | | | | | | | |
| Acadia | 2007-2017 | | | | 91538 (0) | | | |
| Canyon | 2004-2012 | | | | 91495 (0) | | | |
| Canyon | 2015-2017 | | | | | | 91540 (0) M | |
| Jimmy, Full Size | 1978-87 | 88202 (4) | | | | | | |
| Jimmy, S-15 | 1983-94 | 88202 (2) | | | 91438 (0) | | | |
| Jimmy, Downsized | 1995-2001 | | | | 91434 (4) | | | |
| Pickup, Full Size | 1968-87 | | | 88302 (4) I | | | 91403 (6) | |
| Pickup, Full Size | 1988-98 | | | 88302 (2) I | | 91409 (0) | 91404 (2) I | 91406 (0) |
| With 10" Drop Bumper | | | | | | | | 91460 (0) |
| With 12" Drop Bumper | | | | | | | | 91458 (0) |
| Pickup, Classic C/K Series | 1999-2000 | | | | | 91409 (0) | | 91406 (0) |
| 3/4 & 1-Ton | | | | | | | | |
| With 10" Drop Bumper | | | | | | | | 91460 (0) |
| With 12" Drop Bumper | | | | | | | | 91458 (0) |
| Pickup, Sierra, 1500 LD, 1500 HD & 2500 LD | 1999-2006 | | | | | 91409 (2) | | 91454 (0) |
| Pickup, Classic Sierra, 1500 LD & 1500 HD | 2007 | | | | | 91409 (2) | | 91454 (0) |
| Pickup, Sierra, 1500 (New Body Style) | 2007-2017 | | | | | | | 91510 (0) |
| Pickup, Sierra, 2500 HD & 3500 | 2001-2006 | | | | | | | 91477 (0) |
| Shortbed Only | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2007-2010 | | | | | | | 91477 (0) |
| Shortbed Only (Classic & New Body Style) | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2001-2006 | | | | | | | 91478 (0) |
| Longbed Only | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2007-2010 | | | | | | | 91478 (0) |
| Longbed Only (Classic & New Body Style) | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2001-2010 | | | | | | | 91515 (0) |
| Longbed Only w/ 10" Drop Bumper | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2011-2017 | | | | | | | 91527 (0) |
| Longbed Only w/ 10" Drop Bumper | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2011-2017 | | | | | | | 91529 (0) |
| Shortbed Only | | | | | | | | |
| Pickup, Sierra, 2500 HD & 3500 | 2011-2017 | | | | | | | 91525 (0) |
| Longbed Only | | | | | | | | |
| Pickup, S-15 | 1982-93 | 88202 (4) A | | | 91435 (4) | | | |
| Pickup, S-15, Longbed Only | 1982-93 | 88202 (4) | | 88302 (6) **A | 91435 (4) | | | |
| Sonoma (Except Sportside) | 1994-2004 | 88202 (4) A | | | 91436 (0) | | | |
| Sonoma, Sportside | 1994-2004 | | | | 91485 (0) | | | |
| Suburban | 1973-91 | | | | | | 91480 (4) | |
| Suburban, Classic | 1992-2000 | | | | | | 91430 (0) | |
| Terrain | 2010-2017 | | 91512 (0) | | | | | |
| Van, Safari, Standard | 1985-94 | 88202 (0) | 91446 (4) | | | | | |
| Van, Safari, Extended | 1985-2005 | 88202 (0) | 91446 (0) | | | | | |
| Van, Full Size | 1978-95 | | | | | | 91447 (0) | |
| Van, Savanna | 1996-2017 | | | | | | 91431 (0) | |
| Yukon, Classic | 1992-2000 | | | | | | 91430 (0) | |
| Yukon, New Style & XL | 2000-2006 | | | | | | 91472 (0) | |
| HONDA | | | | | | | | |
| Passport | 1998-2002 | | | | 91483 (0) | | | |
| INFINITI | | | | | | | | |
| QX4 | 1996-2003 | | | | 91476 (0) | | | |
| ISUZU | | | | | | | | |
| Axiom | 2002-2004 | | | | 91483 (0) | | | |
| Pickup, Hombre, All | 1996-2000 | | | | 91436 (0) | | | |
| Pickup, i-280 & i-350 | 2006 | | | | 91495 (0) | | | |
| Pickup, i-290 & i-370 | 2007-2008 | | | | 91495 (0) | | | |
| Rodeo | 1998-2004 | | | | 91483 (0) | | | |
| Trooper | 1992-2002 | | | | 91487 (1) | | | |
| JEEP | | | | | | | | |
| Cherokee | 1976-83 | 88203 (2) | | 88302 (4) | | | | |
| Cherokee | 1984-2001 | 88203 (2) | | | 91451 (0) | | | |
| Grand Cherokee | 1993-98 | 88202 (0) | | | 91445 (0) | | | |
| Grand Cherokee | 1999-2004 | | | | 91463 (0) | | | |
| Grand Cherokee | 2011-2017 | | | | 91531 (0) | | | |
| Liberty | 2002-2007 | | | | 91484 (0) | | | |
| Pickup, J-10 & J-20 | 1976-86 | 88202 (4) | | | | | | |
| Wagoneer | 1976-83 | 88203 (4) | | 88302 (6) | | | | |
| JEEP CONTINUED ON NEXT PAGE | | | | | | | | |

(A) May require some exhaust pipe modification, or relocation of tailpipe holder.

(B) Spare tire holder must be moved.

(C) Do not mount frame arm against brake line.

(D) Gas tank must be dropped to install bolts through frame.

(E) Maximum rating on Windstar is 2000 lbs. GTW.

(F) Make sure gas tank filter hose does not rub on hitch.

(G) Full size spare must be moved.

(H) Must relocate spare if equipped with 17" wheels

(I) 1/2 ton only.

(J) 1 1/4" Receiver.

(L) Combination pintle mount (16,000 lbs.) and receiver hitch (10,000 lbs.)

(M) Max. Gross Trailer Weight - 6,000 lbs.

** 4 Wheel Drive Only

(#) = Number of holes to be drilled in frame. Example - Ford Ranger Pickup 1983-2011 Hitch 91440 (0) = 0 holes to be drilled.



Since 1938

2017 CLASS II, III & IV TRAILER HITCH APPLICATIONS

Always check your owners manual for the maximum towing and load capacities for your vehicle.

Questions? Call 800-821-7576 or 816-921-0444 Monday through Friday, 8:00-4:30 CST.

Part numbers printed in red indicate no drilling required.

**SEE
COUNTER
PERSON FOR
SPECIAL
ORDERS**

| ACME APPLICATIONS BY VEHICLE | | Class II Receiver | | Class III Receiver | | Class IV Receiver | | |
|-------------------------------|-------------|--|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--------------------------------------|--|
| | | Universal to 3500 lbs 1 1/4" Receiver | One Piece to 3500 lbs 2" Receiver | Universal to 5000 lbs 2" Receiver | One Piece to 5000 lbs 2" Receiver | Universal to 7500 lbs 2" Receiver | One Piece to 7500 lbs 2" Receiver | One Piece to 10,000 lbs 2" Receiver |
| VEHICLE MAKE & MODEL | YEAR | | | | | | | |
| JEEP - CONTINUED | | | | | | | | |
| Wagoneer | 1984-92 | 88203 (4) | | | | | | |
| Wrangler | 1997-2006 | | 91466 (0) | | | | | |
| Wrangler & Wrangler Unlimited | 2007-2017 | | 91520 (0) | | | | | |
| MAZDA | | | | | | | | |
| Navajo | 1991-94 | 88202 (4) | | | 91464 (2) | | | |
| Pickup, All | 1994-2009 | 88202 (0) | 91475 (0) J | | 91440 (0) | | | |
| Tribute | 2002-2004 | | 91482 (4) | | | | | |
| Tribute | 2005-2011 | | 91499 (1) | | | | | |
| MERCURY | | | | | | | | |
| Mariner (Except Hybrid) | 2005-2011 | | 91499 (1) | | | | | |
| Monterey | 2004-2007 | | 91505 (0) | | | | | |
| Mountaineer | 1996-2001 | 88202 (4) | | | 91464 (0) | | | |
| MITSUBISHI | | | | | | | | |
| Montero | 2001-2004 | | | | 91479 (0) | | | |
| Montero Sport | 1998-2004 | | | | 91486 (0) | | | |
| Raider | 2006-2009 | | | | | | 91508 (0) | |
| NISSAN | | | | | | | | |
| Frontier | 1998-99 | | | | 91457 (4) | | | |
| Frontier | 2000-2004 | | | | 91457 (0) | | | |
| Pathfinder | 1987-95 | | 91453 (4) | | | | | |
| Pathfinder | 1996-2004 | | | | 91476 (0) | | | |
| Pickup, Standard Cab Only | 1970-86 1/2 | 88202 (4) | | | | | | |
| Pickup, All | 1986-97 | | 91439 (2) | | | | | |
| Titan | 2004-2009 | | | | | | | 91501 (0) |
| OLDSMOBILE | | | | | | | | |
| Bravada | 1991-94 | 88202 (2) | | | 91438 (0) | | | |
| Bravada | 1996-2001 | | | | 91434 (4) | | | |
| Silhouette | 1997-2004 | | 91456 (0) | | | | | |
| PLYMOUTH | | | | | | | | |
| Van, Full Size | 1978-80 | 88202 (4) | | | | | | |
| Voyager & Grand Voyager | 1984-90 | 88202 (2) C | | | | | | |
| Voyager & Grand Voyager | 1991-95 | 88203 (0) | | | | | | |
| Voyager & Grand Voyager | 1996-2001 | 88203 (2) G | 91470 (0) | | | | | |
| PONTIAC | | | | | | | | |
| Torrent | 2006-2009 | | 91512 (0) | | | | | |
| Transport | 1997-98 | | 91456 (0) | | | | | |
| Montana | 1999-2005 | | 91456 (0) | | | | | |
| Montana SV6 | 2005-2007 | | 91456 (0) | | | | | |
| SATURN | | | | | | | | |
| Outlook | 2007-2010 | | | | 91538(0) | | | |
| Relay | 2005-2007 | | 91456 (0) | | | | | |
| Vue (Except Redline) | 2002-2007 | | 91512 (0) | | | | | |
| SUZUKI | | | | | | | | |
| Sidekick | 1989-98 | 88202 (0) | | | | | | |
| Vitara & Grand Vitara | 1999-2005 | 88202 (0) | 91468 (0) | | | | | |
| XL7 | 2002-2006 | 88202 (0) | 91468 (0) | | | | | |
| TOYOTA | | | | | | | | |
| 4-Runner | 1996-2003 | | | | 91467 (0) | | | |
| Pickup, T-100, All | 1993-98 | | | | 91433 (0) | | | |
| Pickup, Tacoma, All | 1995-2004 | | | | 91441 (0) | | | |
| Pickup, Tacoma, All | 2005-2015 | | | | 91509 (0) | | | |
| Pickup, Tundra | 2000-2006 | | | | | 91409 (4) | 91469 (2) | |
| Pickup, All | 1984-89 | 88202 (4) | | | | | | |
| Pickup, All | 1984-94 | | | | 91442 (0) | | | |
| VOLKSWAGEN | | | | | | | | |
| Routan | 2009-2012 | | 91514 (0) | | | | | |

(A) May require some exhaust pipe modification, or relocation of tailpipe holder.
 (B) Spare tire holder must be moved.
 (C) Do not mount frame arm against brake line.
 (D) Gas tank must be dropped to install bolts through frame.

(E) Maximum rating on Windstar is 2000 lbs. GTW.
 (F) Make sure gas tank filter hose does not rub on hitch.
 (G) Full size spare must be moved.
 (H) Must relocate spare if equipped with 17" wheels
 (I) 1/2 ton only.

(J) 1 1/4" Receiver.
 (L) Combination pintle mount (16,000 lbs.) and receiver hitch (10,000 lbs.)
 (M) Max. Gross Trailer Weight - 6,000 lbs.
 ** 4 Wheel Drive Only

(#) = Number of holes to be drilled in frame. Example - Ford Ranger Pickup 1983-2011 Hitch 91440 (0) = 0 holes to be drilled.

Custom Fit One-Piece Welded Hitches Powder Coat Finish for Durability Easy to Follow Instructions

- Class II rated up to 3,500 lbs.
- Class III rated up to 5,000 lbs.
- Class IV rated up to 10,000 lbs.

MANY NO-DRILL APPLICATIONS:

- Chevy, Dodge & Ford Full Size Trucks
 - Chevy & Dodge Full Sized Vans
- Suburbans, Cherokees & Explorers
- Tahoes, Yukons, Rangers & S-10s